





Turbo Ring





1





2





3 Turbo Ring



MSTR/HEAD Model : EDS-518E-SS-SC-4GTXSFP IP : 192.168.127.253 MAC Address : 00-90-E8-5C-4E-A3 STATE
CPLR/TAII Name : Serial No : TAFJD1040561 Firmware Version : V5.1 build 16072215 PWR1
Location : Switch Location ABC-02-USB-T : Device Not Present PWR2 FAULT

Home Redundant Protocol

Protocol Turbo Ring V2

Status

- Multicast
- QoS
- Security
- DHCP
- SNMP
- Industrial Protocol
- Diagnostics
- Monitoring

Active Protocol None

Ring	Role	Turbo Ring Status	1st Port Status
Ring 1	--	--	--
Ring 2	--	--	--

Ring Coupling	Role	Primary Port Status	Backup Port S
Ring Coupling	--	--	--

Settings

Ring 1 Ring 2

Set as Master Set as Master

Redundant Ports 1st Port G1 2nd Port G2

Redundant Ports 1st Port G3 2nd Port G4

Ring Coupling Enable

Settings

Ring 1 Ring 2

Set as Master Set as Master

Redundant Ports 1st Port G3 2nd Port G4

Redundant Ports 1st Port G1 2nd Port G2

Ring Coupling Enable

Coupling Mode Dual Homing

Primary Port 1

Backup Port 2

Apply

Turbo Ring



